Poll Res. 39 (November Suppl. Issue) : S192-S195 (2020)

Copyright © EM International ISSN 0257-8050

THE IMPACT OF SEPTIC TANKS ON THE GROUNDWATER: SURVEY RESULTS IN A RURAL AREA OF MOROCCO, AFRICA

S. EL HALAS¹, B. CHARAF¹, M. OUHSSINE² AND B. HSI³

¹Department of Applied Environment, University Hassan First, Settat, Morocco ²Department of Biology, University Ibn Tofail, Kenitra, Morocco ³Department of Economics and Management, University Mohammed Fifth, Rabat, Morocco

(Received 27 June, 2018; accepted 10 August, 2020)

ABSTRACT

In order to deduce the impact of septic tanks on the water, the soil, the vegetal, animal and man, a survey was conducted at Sidi Ayache region in the province of Kenitra, Morocco. The purpose of this survey is the evaluation of the quality of the groundwater in the study area and to have through the testimony of the inhabitants, a return on the various uses of water wells. Four hundred and thirteen households were affected by this questionnaire. Preliminary results of the survey revealed that most people doubt the quality of well water. They claim that all diseases observed in the region could come from the poor quality of water wells having a bad taste and therefore not potable. It was also observed that in some households, there is no respect of distance between septic tanks and wells. There is even a household that has transformed the well to a septic tank. This behavior and others may cause adverse effects on the components of the environment. To confirm this hypothesis, we envisage achieving analysis of well water in the laboratory.

KEY WORDS: Investigation, Septic tanks, Groundwater, Wells, Kenitra, Morocco.

INTRODUCTION

The health of human beings, especially in rural areas, has recently attracted the increased attention of academics as well as policy makers (Cairncross, and Feachem, 2018). On the first hand, some of this attention has focused on the cause of diseases (Prüss-Ustün, 2014). And on the other hand, there is the growing body of research on environmental impact (Kolsky, 1993). In particular, examining not only health problems, but also broader issues of septic tanks installed in the rural areas (Mallin, 2013).

Septic tanks are generally a source of contamination and pollution of the groundwater, therefore the contamination of the water wells (Reay, 2004).

In my rural area of study, located almost 12 kilometers from the city of Kenitra in Morocco, it was observed outbreaks of water-borne diseases, like diarrhea and other intestinal diseases. Although the region has no drinking water system, which lead the population to use well water for drinking.

Therefore, groundwater must be a major cause of these waterborne diseases.

PURPOSE

In order to deduce the impact of septic tanks on the water, the soil, the vegetation, animal and man, an investigation was conducted at Sidi Ayache in the province of Kenitra.

The purpose of this survey was the evaluation of the quality of the groundwater in the study area.

MATERIALS AND METHODS

Study location. "Sidi Ayache" is the rural area of study, located almost 70 kilometers from the capital Rabat in Morocco.



Fig. 1. Rural area of the study

Survey. A questionnaire was established to have, through the testimony of the inhabitants, a return on the quality of water wells. Four hundred and thirteen households were affected by this questionnaire. The purpose of the questionnaire is to obtain information on the harmful effects that can cause septic systems both on people's health as well as on other environmental components.

We also attempted to determine the expectations of the inhabitants of the study area concerning water supply, improvement of water-related services and construction of septic tanks with design standards in this region.

RESULTS

Interviewer's gender. The sample surveyed represents almost 58% men and 42% women.




Fig. 2. Interviewer's gender

Wells: covered/uncovered

Almost 63% of the interviewees take care of their wells and cover them while about 37% do not.



Fig. 3. Conditions of the wells

Depth of the wells.

The percentage of respondents who have a depth between 21-23m occupies almost 58%. Depth measurements between 18-20 and 24-26 share the rest of the circle.




Fig. 4. Depth of the wells

Construction type of septic tanks. The majority of the septic tanks is built by rocks.



Fig. 5. Construction type of septic tanks

Depth of septic tanks. The majority of septic tanks has a depth between 3 and 5 meters.




Fig. 6. Depth of septic tanks

Distance between septic systems and wells. Only 18% of residents leave a sufficient distance between the septic systems and wells which varies between 20 and 25m.




Fig. 7. Distance between septic systems and wells

Appreciation of the water wells. The majority of residents doubt of the quality of their well water if it is safe for drinking or not.



Fig. 8. Appreciation of the water wells

Taste change of the water wells over time. Most of residents noticed a change in the taste of the water wells. Almost 74% have noticed a change in the taste of the well while the quarter has nothing felt.




Fig. 9. Taste change of the water wells over time

Existence of health problems. People with health problems colonize the entire circle, only 19.5% said they don't have health problems.




Fig. 10. Existence of health problems

Health problems. Among the most common diseases in the study area are diarrhea, fever and allergy.




Fig. 11. Health problems

Diarrhea is the most repetitive.

The cause of diseases. The majority of individuals declare that the water wells can be a major cause of disease frequented.




Fig. 12. Possible causes of diseases

DISCUSSION

- This survey was carried out in the framework of my research on the population in order to obtain opinions about their concerns, expectations and wishes to improve the whole services, namely the quality of the septic tanks in the region. 413 households were affected by this survey.
- The purpose of the survey is to obtain information on the harmful effects that can cause septic systems both on people's health as well as on other environmental components.
- Preliminary results of the survey revealed that most of residents doubt the quality of well water. They claim that all diseases observed in the region could come from the poor quality of water wells having a bad taste and therefore not potable.
- It was also observed that in some households, there is no respect of distance between septic tanks and wells. There is even households that has transformed the well into septic tank. This behaviour and others may cause adverse effects on the components of the environment.

CONCLUSION

Preliminary results of the survey revealed that most of residents people doubt the quality of well water.

They claim that all diseases observed in the region could come from the poor quality of water wells having a bad taste and therefore not potable.

It was also observed that in some households, there is no respect of distance between septic tanks and wells. There is even a household that has transformed the wells to a septic tank. This behaviour and others may cause adverse effects on the components of the previously mentioned environment.

REFERENCES

- Cairncross, S. and Feachem, R. 2018. Environmental Health Engineering in the Tropics: Water, Sanitation and Disease Control.
- Kolsky, P. J. 1993. Water, sanitation and diarrhoea: The limits of understanding. *Trans. R. Soc. Trop. Med. Hyg.* 87: 43-46.
- Mallin, M. A. 2013. Septic Systems in the Coastal Environment. Multiple Water Quality Problems in Many Areas. Elsevier B.V..
- Northwest, I. 2005. Septic System Impact on Surface Waters. A Review for the Inland Northwest Table of Contents, pp. 1-32.
- Prüss-Ustün, A. 2014. Burden of disease from inadequate water, sanitation and hygiene in low- and middle-income settings: A retrospective analysis of data from 145 countries. *Trop. Med. Int. Heal.* 19(8): 894-905.
- Reay, W.G. 2004. Septic tank impacts on ground water quality and nearshore sediment nutrient flux. *Ground Water.* 42(7): 1079-1089